

Report ID: 26,362,812 Version: 3 21 Nov 2024 Created:

Make:	Mazda	Model:	CX-9	Body Style:	SUV		Pass	Fail	N/A
Year:	2011	Registration:	GDN469	Reg Expiry:	24 Nov 2024	Engine			
WoF Expiry:	22 Apr 2025	Odometer:	183,234 Kms	Good No:	26362812	Oil level	V		
VIN:	JM0TB10A4C0308010	Next Service:	193000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	V		
						Performance	~		
Key:	S SC	-0	S D SC S	-01-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent	s sc			715	S D SC	Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	S S	Clutch			~
P = pin dent	110				게	CV joints	~		-
* = decals	SDSC 916			-Jul-	SR SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S D S S S D S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
								mm	
						Right front		.0	mm
						Left rear		.0	mm
Condition	as During Padulas	naction	Deri			Right rear			
Conditions During Body Inspection: Dry						Spare	5		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average						~		
Demolo	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	Comments					Window winder RL	~		
Camera vie						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
Road Conditions During Test Drive: Dry							2		
Road Con	ditions During Fest	t Drive:	Dry			Central locking Remote locking	v		
Engine Ti	ming Mechanism:	Timing	Chain				~		
-	of Cam Belt Replac	-	lot Applicable	Kms:		Sat. Nav. (basic test only)			~
						Reversing camera		~	
Inspected by: Gary Adams Date: 15 Oct 2024									

I have read and understood this condition guide.

Name:

Signature: