

Report ID: 26,364,869 Version: 1 14 Oct 2024 Created:

Make:	Nissan	Model:	Skyline	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2010	Registration:	MED956	Reg Expiry:	29 Nov 2024	Engine				
WoF Expiry:	03 Jul 2024	Odometer:	167,360 Kms	Good No:	26364869	Oil level		~		
VIN:	7AT0DH12X18101355	Next Service:	ooo kms	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent	- HE			715	FILL S	Operation	~			
R = rust PT = paint defe				$\prod$		Noise	~			
C = crack				$+ \mathbf{\nabla}$		] Clutch	-		~	
P = pin dent					세비	CV joints	~		<b>–</b>	
* = decals	616			The	ETTP-	Wheel bearings	~			
SC = stone chi		20		1al	¥ —	Brakes				
W = significan	t scuffs	$-\emptyset$				Performance	~			
		Note: som	ne defects & blemishe	s may not be disr	laved in the diagram	Hand Brake	~			
Body Insp	pection Comments			5 may not be any		Tyres (lowest observed tre	•	oftyre		
						Left front 5 mm				
						Right front			mm	
						Left rear		5	mm	
			_			Right rear		4		
Conditions During Body Inspection: Dry							4 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension				
Rwd						Suspension performance	~			
linita						Steering performance				
						Shock absorbers	~		<sup> </sup>	
							~			
						Air Conditioning / Heater				
Interior C	omments					Operation	~			
Average						Electrical / Accessories				
Seats						Head lights	~			
Carpets	Average					Tail lights	~			
	Average					Indicators	~			
Panels						Dashboard warning light				
Dashboa	Good Good					Wipers (front & rear)	~			
						Window winder FL	~		ļ!	
General	Comments					Window winder FR	~			
General Comments Both rear window Up not working from master switch, glove box broken, R/ wing mirror broken, engine oil						Window winder RL	~			
	g rock leaking, power st			,	onen,engine on	Window winder RR	~		ļ!	
						Rear view mirrors	~		<u> </u>	
						Radio (basic test only)	~		ļ!	
						CD (basic test only)	~			
						Number of keys	1	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		ļ!	
Enging Ti	ming Mochanisme	Timina	Chain			Remote locking	~			
-	ming Mechanism:	Timing (		Kan i		Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	d by: Marlon Espena					Date: 14 Oct 2	124			
inspected										

I have read and understood this condition guide.

Name: .....

Signature: .....