

Report ID: 26,364,951 3 Version: 13 Dec 2024 Created:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year:	2022	Registration:	PRD925	Reg Expiry:	30 Sep 2024	Engine			L
WoF Expiry:	31 Dec 2025	Odometer:	17,262 Kms	Good No:	26364951	Oil level		~	
VIN:	TMAJB81BVNJ233431	Next Service:	32,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~	-	
						Performance	~		
	port is not a warranty	oration is made	for and milaan	Darte have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
					S	Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				715	SD SD	Operation	~		
PT = paint defe	ect NP			$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HIC				7414	CV joints	~		
* = decals	- All			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$\neg \varnothing$	<u> </u>			Performance	~		
Dedulmen		Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			L es)
						Left front	4.		mm
						Right front	4.		mm
						Left rear	4.		mm
Conditions During Body Inspection: Dry						Right rear	-		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Fwd						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		<u> </u>
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FR	V		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
						Number of keys	1		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	· •		
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
						-			L
Inspected by: Marlon Espena Date: 28 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....