

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments Rwd

Dry

		Operation	~			
Interior Comments		Electrical / Accessories	Electrical / Accessories			
Seats	Average	Head lights	~			
Carpets	Average	Tail lights	~			
		Indicators	~			
Panels	Good	Dashboard warning ligh	ts 🖌			
Dashboard	Good	Wipers (front & rear)	~			
		Window winder FL	~			
		Window winder FR	~			
General Comments Service light on,L wheel bearing or wheel noise .coolant leak mark,		Window winder RL	~			
		Window winder RR	~			
		Rear view mirrors	~			
		Radio (basic test only)	~			
		CD (basic test only)			~	
		Number of keys	1			
Road Condition	ns During Test Drive: Dry	Central locking	~			
		Remote locking	~			

Kms:

Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable

Inspected by: Marlon Espena

14 Oct 2024 Date:

Sat. Nav. (basic test only)

Reversing camera

I have read and understood this condition guide.

Name:

Signature:

V

Report ID: 26,365,276 Version: 1 14 Oct 2024

Pass

V

V

V

V

V

V

V

~

V

Right rear

Suspension

Suspension performance

Steering performance

Air Conditioning / Heater

Shock absorbers

Spare

4.5

4.5

2.5

3

V

V

~

N/A

Fail

~

V

V

V

V

mm

mm

mm

mm

1

N/A