

Basic Vehicle Condition Guide

Report ID: 26,365,921


Version: 1

Created: 16 Oct 2024

Make: Model: Mercedes-Benz CLA45 **Body Style:** Sedan Year: 2014 Registration: PGA935 Reg Expiry: 10 Nov 2024 WoF Expiry: **Odometer: Good No:** 03 May 2025 88,553 Kms 26365921 VIN: WDD1173522N14845 Next Service: 96,313 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

| Conditions | During | ı Bodv | Inspection: | Drv |
|------------|--------|--------|-------------|-----|
| | | | | |

Under Carriage & Under Bonnet Inspection Comments

All wheel drive

| Interior Commen | <u>ts</u> |
|-----------------|-----------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

| | _ |
|---------|----------|
| General | Comments |

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Andre Richardson Inspected by:

| Cleate | u. K | J OCT 2 | 024 |
|------------------------------|--------------|----------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | V | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | <i>V</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | L es) |
| Left front | I | | mm |
| Right front | | 5 | mm |
| Left rear | | <u> </u> | mm |
| Right rear | | 5 5 | mm |
| Spare | Ì | No | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | V | | |
| Electrical / Accessories | | | |
| Head lights | V | | |
| Tail lights | ~ | | |
| Indicators | | | |
| Dashboard warning lights | · | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | • | | |
| Window winder FR | ~ | | |
| Window winder RL | | | |
| | V | | |
| Window winder RR | - | | |
| Rear view mirrors | ' | | |
| Radio (basic test only) | <i>V</i> | | |
| CD (basic test only) | ' | | |
| Number of keys | 1 | | |
| Central locking | ' | | |
| Remote locking | ' | | |
| Sat. Nav. (basic test only) | \(\times \) | | |
| Reversing camera | | | |
| | | | |

16 Oct 2024

Signature:

Date:

Name: