

I have read and understood this condition guide.

Report ID: 26,366,210 Version: 1 15 Nov 2024 Created:

Signature:

Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Year: 2	2016	Registration:	KEF980	Reg Expiry:	17 Nov 2024	Engine			
WoF Expiry: 1	13 Nov 2025	Odometer:	159,774 Kms	Good No:	26366210	Oil level	~		
	TMAJ281ASHJ280840	Next Service:	174000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	ort is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanic	cal inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	P SC SC			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			215	S SC	Operation	~		
PT = paint defect				$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	SPSC DR				74 <u>11</u> 4	CV joints	~		
* = decals				10	ELC SC	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant s	SC		SC P SC			Performance	~		
Body Inspe	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Nudge bar front bumper,roof racks,minor stone chips windscreen ,						Tyres (lowest observed tread	depth	of tyre	es)
Addge our nort ouripersoor racio, minor storie erips windsereeri,						Left front 6.3			mm
						Right front	6.	2	mm
						Left rear	5.	8	mm
Conditions During Body Inspection: Dry						Right rear	5.7 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Compete	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Derbha	ے۔ Good					Wipers (front & rear)	~		
Dashboard	u					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	<			
Drives okay, Recent Service					Window winder RR	1			
Fresh WOF						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Time	ing Machanisme	T:	- hain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence of	or Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	Inspected by: Donovan Matara Date: 18 Oct 2024								

Name: