

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Coolant condition V Performance SC SP SC SC Key: Radiator / Hoses (visual) V S = scratch Transmission D = dent S S SC Operation V R = rustNoise V PT = paint defect C = crackClutch P = pin dent CV joints ~ SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs S S D Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake ~ **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front 6.0 **Right front** 6.2 Left rear 4.0 **Right rear** 4.0 Conditions During Body Inspection: Dry Spare Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Average Seats Head lights 1 Tail lights 1 Average Carpets Indicators ~ Average Dashboard warning lights 1 Panels Wipers (front & rear) 1 Average Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 1

		· .
Road Conditions During Test Drive: Dry	Central locking	~
	Remote locking	~
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)	
Evidence of Cam Belt Replacement: Not Applicable Kms:	Beversing camera	~

Chris McQuade Inspected by:

15 Oct 2024 Date:

Report ID: 26,367,342 Version: 4 Created: 19 Oct 2024

Fail

Pass

~

V

1

~

Noise

N/A

V

mm

mm

mm

mm

~

Yes

I have read and understood this condition guide.	
--	--

Name:

Signature: