

Report ID: 26,370,237 Version: 1 17 Oct 2024 Created:

Make:	MG	Model:	4	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2023	<b>Registration:</b>	QFQ729	<b>Reg Expiry:</b>	23 Oct 2025	Engine	•		
WoF Expiry:	12 Oct 2026	Odometer:	13,976 Kms	Good No:	26370237	Oil level	~		
VIN:	LSJWH4097PN201656	Next Service:	0	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged to	r an additional o	narge.	Coolant condition	~		
			S SC			Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	s sc			210	HIVS	Operation	~		
PT = paint defe		r I		$\left[ \left( \right) \right]$	70111	Noise	~		
C = crack						Clutch			~
P = pin dent	HIR				74JUL	CV joints	~		
* = decals	sc 916			10	ELC'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Body Insr	ection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front	5.6 mm		
						Right front	5.	.5	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.4 mm		mm
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	has chargi	ng cable in rear o	of car,			Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Cone	ditions During Test	Drive:	Dry			Central locking	~		
						Remote locking	~		
-	ning Mechanism:	Timing (				Sat. Nav. (basic test only)	~		
Evidence of	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
I	law Departure Mar					D-t- 17.0-/ 20/	24		
Inspected by: Donovan Matara Date: 17 Oct 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....