

Report ID: 26,376,093 Version: 2 25 Oct 2024 Created:

Make:	Subaru	Model:	XV	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2014	Registration:	QDL368	Reg Expiry:	20 Nov 2024	Engine			1	
WoF Expiry:	03 Aug 2025	Odometer:	145,367 Kms	Good No:	26376093	Oil level	~			
VIN:	7AT0GF1XX23012878	Next Service:	148,700 kms	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0		-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust S						Operation	~			
R = rust PT = paint defe				\prod	JUIL	Noise	~			
C = crack				+		Clutch			~	
P = pin dent					세비	CV joints	~			
* = decals	sc 916			-NL	ELLEN	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance	~			
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~			
	pection Comments	Note: Joh		indy not be disp		Tyres (lowest observed tread	•	oftyre	() ()	
Tyre mobility kit available Stone chips in windscreen					Left front 7.0 mm					
						Right front			mm	
						Left rear	7.		mm	
			_			Right rear		-	mm	
Conditions During Body Inspection: Dry						Right rear 9.0 mr Spare N/A				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
4wd						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	-			
						Air Conditioning / Heater	~			
						J				
Interior Comments						Operation V				
Good						Electrical / Accessories Head lights				
Seats							~			
Carpets	Good					Tail lights	~			
	Good					Indicators	~			
Panels						Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
						Window winder FL	~			
General	Comments					Window winder FR	~			
	<u>comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Tir	ming Mechanism	Timing				Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
Evidence		ement: N	lot Applicable	NITIS:		Reversing camera	~			
Inspected	Inspected by: Vasanthakumar Mayilswamy Date: 21 Oct 2024									

I have read and understood this condition guide.

Name:

Signature: