

Report ID: 26,376,933 Version: 2 25 Oct 2024 Created:

Make:	Suzuki	Model:	Celerio	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2020	Registration:	NEF315	Reg Expiry:	29 Nov 2024	Engine			
WoF Expiry:	07 Nov 2025	Odometer:	7,346 Kms	Good No:	26376933	Oil level	~		
VIN:	MMSLFE42S00204956	Next Service:	17,350	Service Histor	<b>y:</b> No	Smoke & fumes	~		
Net a This as						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S		S SC S SC		S D	Performance	~		
Key:		-0		5(0)-		Radiator / Hoses (visual)	~		
S = scratch	TE				Tan	Transmission	1		1
D = dent R = rust	s sc w	1		710	EIIVS	Operation	~		
PT = paint def	ect NP	IT I				Noise	~		
C = crack					SC	Clutch			~
P = pin dent	ING HIS				74114	CV joints	~		
* = decals	DSC 91			- John		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC P						Performance	~		
Podula-	action Comments	Note: son	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres			es)
									mm
						Right front		.5	mm
						Left rear	6		mm
Conditions During Rody Inspection: Dry						Right rear	6		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Battery goo	od					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights			
						Tail lights	~		
Carpets	Good						~		
Danala	Average. S	Scratches.				Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FL	<i>v</i> <i>v</i>		
General (	<u>Comments</u>					Window winder RL	~		
A/c and rev camera good. No nav						Window winder RE	v v		
Radio not v	vorking					Rear view mirrors	~		
						Radio (basic test only) CD (basic test only)	<b>v</b>		
						Number of keys	<b>/</b>		
							2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		ernerne, p		11113.		Reversing camera	~		
Inspected by: Reuben Harvey Date: 23 Oct 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....