


<b>Make:</b> Nissan	<b>Model:</b> Navara	<b>Body Style:</b> Utility
<b>Year:</b> 2005	<b>Registration:</b> CNJ683	<b>Reg Expiry:</b> 27 Nov 2024
<b>WoF Expiry:</b> 11 Jan 2025	<b>Odometer:</b> 334,152 Kms	<b>Good No:</b> 26377288
<b>VIN:</b> JN1APGD22U0057839	<b>Next Service:</b> 342,000 kms	<b>Service History:</b> No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

- S = scratch
- D = dent
- R = rust
- PT = paint defect
- C = crack
- P = pin dent
- \* = decals
- SC = stone chips
- W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Stone chips left A pillar, left cab corner dented and scuffed  
 Left rear wheel centre cap missing, tool box not fixed to deck  
 Right cab corner gouged, stone chips right A pillar  
 Chips in windscreen, spider rust on roof

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Large oil leaks  
 Underbody surface rust

**Interior Comments**

Seats	holes right seat base
Carpets	large holes in right carpet
Panels	Average
Dashboard	Average

**General Comments**

Smoke on cold start up  
 Reversing lights not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes		✓	
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	2.5	mm	
Right front	2	mm	
Left rear	4	mm	
Right rear	6	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights		✓	
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)			✓
Number of keys	1		
Central locking			✓
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Dean Sinclair

Date: 22 Oct 2024

I have read and understood this condition guide. Name: ..... Signature: .....