

I have read and understood this condition guide.

Report ID: 26,378,731 Version: 1 22 Oct 2024 Created:

Signature:

Make:	Mazda	Model:	CX-3	Body Style:	SUV		Pass	Fail	N/A
Year:	2021	Registration:	NNU299	Reg Expiry:	15 Dec 2024	Engine	1	I	I
WoF Expiry:		Odometer:	74,920 Kms	Good No:	26378731	Oil level	~		
VIN:	JM0DK2W7A0165804	Next Service:	81000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	boon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust S D SC S S						Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	r		
C = crack						Clutch			~
P = pin dent	sc dR				74114	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – significan			D			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Driver door seal torn						Tyres (lowest observed tread depth of tyres)			
Rear windscreen wiper worn						Left front 5			mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	ision		
Front whee	l drivee					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)		~	
	iu l					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	
Road Conditions During Test Drive: Wet Central locking							~		
	ning Mashaulau	T !	^c hain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Xinghui Lin Date: 22 Oct 2024									
Inspected by, Amgharem Date: 22 Oct 2024									

Name: