

Basic Vehicle Condition Guide

Report ID: 26,380,006


Version:

Created: 03 Dec 2024

Make: Nissan Model: Fuga **Body Style:** Sedan Year: 2014 Registration: **Reg Expiry:** WoF Expiry: **Odometer:** 28 Nov 2025 116,149 Kms **Good No:** 26380006 VIN: 7AT0DH8GX24202736 Next Service: 126,000km **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

N/A Pass Fail Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 6.5 Right front 6.5 mm Left rear mm Right rear 5.5 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera

I have read and understood this condition guide.

Blair Robertson

Name:			

03 Dec 2024

Date: