

Basic Vehicle Condition Guide

Report ID: 26,380,081

Version: 1

Created: 21 Nov 2024


Make:ToyotaModel:HiaceBody Style:VanYear:2019Registration:Reg Expiry:

 WoF Expiry:
 19 Nov 2025
 Odometer:
 69,463 Kms
 Good No:
 26380081

 VIN:
 7AT0H60FX24027727
 Next Service:
 84,500 kms
 Service History:
 No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>i</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Dean Sinclair Date: 21 Nov 2024

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	> > > >		
Performance	~		
Noise	>		
Cooling System			
Coolant condition	~		
Performance	>		
Radiator / Hoses (visual)	/		
Transmission			•
Operation	V		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	/		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4.	.5	mm
Right front	4		mm
Left rear	5		mm
Right rear	4	1	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	'		
Tail lights	~		
Indicators	'		
Dashboard warning lights	~		
Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			'
Number of keys	2		ı
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			'

I have read and understood this condition guide.

Name:			