

## **Basic Vehicle Condition Guide**

Report ID: 26,381,154


Version: 1

Created: 12 Nov 2024

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2018 Registration: LGB428 **Reg Expiry:** 19 Mar 2025 WoF Expiry: **Odometer:** 07 May 2025 132,094 Kms **Good No:** 26381154 VIN: MR0KA3CD101205862 Next Service: 133,215kms **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Large dent in drivers door panel. Paint worn through to metal on top of right side sill, under drivers door. Both left & right side running boards are bent.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Average			
Dashboard	Good			

## **General Comments**

Clutch starting to slip under load, clutch worn. Right front headlight is not working on low beam. Interior roof lights are not working. Fabric on interior panel on drivers door is worn & has a hole in it. Cd player is not working, cd stuck inside unit.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

11 Nov 2024 Inspected by: Jason Young Date:

Name: .....

	I _			
	Pass	Fail	N/A	
Engine		1	1	
Oil level	~			
Smoke & fumes	v v			
Performance	~			
Noise	<b>'</b>			
Cooling System		1	1	
Coolant condition	\( \triangle \)			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	•			
Noise	~			
Clutch		~		
CV joints	-			
Wheel bearings	<b>'</b>			
Brakes			1	
Performance	<b>'</b>			
Hand Brake	· ·			
Tyres (lowest observed tread				
Left front		.0	mm	
Right front	6.0		mm	
Left rear	5.0		mm	
Right rear	3.0		mm	
Spare		Yes		
Suspension			1	
Suspension performance	<i>v</i>			
Steering performance	•			
Shock absorbers				
Air Conditioning / Heater				
Operation   Electrical / Accessories				
Head lights				
Tail lights	•/			
Indicators	•			
Dashboard warning lights	\( \triangle \)			
Wipers (front & rear)	•			
Window winder FL				
Window winder FR	<b>V</b>			
Window winder RL	✓ ✓			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)		<b>1</b>		
Number of keys	3			
Central locking	•/			
Remote locking	<i>y</i>			
Sat. Nav. (basic test only)			1	
Reversing camera	~			
eversing curriera				

Signature: .....