

Report ID: 26,382,821 Version: 2 24 Oct 2024 Created:

Make:	LDV	Model:	Deliver 9	Body Style:	Van		Pass	Fail	N/A
Year:	2022	Registration:	PDN284	Reg Expiry:	29 Mar 2025	Engine			
WoF Expiry:	30 Mar 2025	Odometer:	48,848 Kms	Good No:	26382821	Oil level	~		
VIN:	LSH14J7C3NA085528			Service History		Smoke & fumes	~		
	25111457 (2514) (005520		00,000 km		. 103	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:	D		S P S D		SDRC	Performance	~		
S = scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	MID			$\langle \rangle \rangle$	HUY	Operation	~		
PT = paint def	ect				P P	Noise	~		
C = crack						Clutch			~
P = pin dent * = decals	sc dl			SL-	18145	CV joints	~		
* = decals SC = stone chips						Wheel bearings			
W = significant scuffs						Brakes			
	D	\sim	S D S D		S D R	Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Bumper L/H garnish& tow hook cover missing.						Tyres (lowest observed tread depth of tyres)			
R/R quarter accident damage (flares&moulds). Rear bumper accident damaged.						Left front 6			mm
Rear bump	er accident damaged.					Right front		5	mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
RWD.						Suspension performance	~		
Rear under	side surface rust.					Steering performance	V		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	•		
Seats						Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Derrolo	Good					Dashboard warning lights	-	~	
Panels						Wipers (front & rear)	~	~	
Dashboa	Good					Window winder FL			
							v		
General (omments					Window winder FR	~		
General Comments L/H wing mirror glass damaged.						Window winder RL			~
Fault codes.					Window winder RR			~	
Airbag light ON. Rear camera not working.					Rear view mirrors	~			
	- · · · · · · · · · · · · · · · · · · ·					Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine T:	ming Machaniana	T:	- 			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Imraan Bryant Date: 24 Oct 2024									
Inspecte	d by: Imraan Bryant					Date: 24 Oct 202			

I have read and understood this condition guide.

Name:

Signature: