

Report ID: 26,384,798 Version: 2 03 Dec 2024 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2020		NCP668	Reg Expiry:	15 Apr 2025	Engine			
WoF Expiry:	27 Oct 2024	Odometer:	74,867 Kms	Good No:	26384798	Oil level	~		
VIN:	KMFWBX7KMLU14195			Service History		Smoke & fumes	~		
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,. 105	Performance	~		
	oort is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
				_		Performance	v v		+
Key:	S	-0	DR SP		DP	Radiator / Hoses (visual)	<i>v</i> <i>v</i>		+
S = scratch	Sec	20			\sim	Transmission	V		
D = dent				1 - L	BID SPTC				1
R = rust				10		Operation	~		
PT = paint defe	ect III			$ \cup$		Noise	~		<u> </u>
C = crack P = pin dent	Hb		لالمار			Clutch			~
* = decals	PSC DC				ENR DPT	CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs S S W S D S D S D						Brakes		1	T
						Performance	~		<u> </u>
Body Insp	ection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Tailgate seal damaged.						Tyres (lowest observed tread depth of tyres)			
Front bumper refit. L/H sunvisor glass cracked.						Left front	9	.0	mm
L/F rim damaged,						Right front	9.0		mm
L/H&R/H sill dented.						Left rear	8.0 r		mm
Conditions During Body Inspection: Dry					Right rear	8.0 mm		mm	
					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
RWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights		~	
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL			~	
R/F park light not working. L/H headlight not working.					Window winder RR			~	
_, r neddilg						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1	I	4
Road Conditions During Test Drive: Dry						Central locking	~		
			2.y			Remote locking	~		1
Engine Tir	ming Mechanism:	Timing (Thain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Imraan Bryant Date: 31 Oct 2024									

I have read and understood this condition guide.

Name: