

Basic Vehicle Condition Guide

Report ID: 26,386,044


Version: 1

Created: 25 Oct 2024

Make: Model: Hyundai lload **Body Style:** Van Year: 2013 Registration: GTF78 Reg Expiry: 10 Jul 2025 WoF Expiry: **Odometer: Good No:** 15 Jul 2025 99,077 Kms 26386044 VIN: KMFWBX7KMDU5499 Next Service: 112,000 km **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

RWD.

Oil leak underside.

| <u>Interior Comments</u> | | |
|--------------------------|---------|--|
| Seats | Poor | |
| Carpets | Poor | |
| Panels | Average | |
| Dashboard | Poor | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Imraan Bryant

| Cleate | u. 2. | J OCT 2 | 024 |
|---|--------------|---------|------------|
| | Pass | Fail | N/A |
| Engine | • | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | - | 1 |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | 1 |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | _ | | \ <u>\</u> |
| CV joints | ~ | | • |
| Wheel bearings | • | | |
| Brakes | | | |
| Performance | | | |
| Hand Brake | | | |
| | l donth | of the |) |
| Tyres (lowest observed tread Left front | | | |
| | 8 | | mm |
| Right front | 8 | | mm |
| Left rear | 7 | | mm |
| Right rear | | 7 | mm |
| Spare | | Yes | |
| Suspension | | | 1 |
| Suspension performance | <i>V</i> | | |
| Steering performance | <i>V</i> | | |
| Shock absorbers | • | | |
| Air Conditioning / Heater | | 1 | 1 |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | \(\times \) | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ~ |
| Window winder RR | | | ~ |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | • |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| | | | V |
| Sat. Nav. (basic test only) | | | |
| Sat. Nav. (basic test only) Reversing camera | ~ | | |

I have read and understood this condition guide.

Name:

Signature:

25 Oct 2024

Date: