

Report ID: 26,387,520 Version: 1 Created: 30 Oct 2024

Make:	Mini	Model:	Cooper	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:	JNL462	Reg Expiry:	16 Feb 2025	Engine		L	1
WoF Expiry:	15 Aug 2025	Odometer:	112,964 Kms	Good No:	26387520	Oil level	~		
VIN:	WMWZB32020WT857	Next Service:	119900	Service Histor	y: No	Smoke & fumes	V		-
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		1
						Performance	~		+
Key:	S SC	-0	S SC S SC	-01-	s	Radiator / Hoses (visual)	~		+
S = scratch						Transmission			1
D = dent	SC DI			ZIS	S SC	Operation	~		T
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+		Clutch			~
P = pin dent					741L	CV joints	~		<u> </u>
* = decals	sc 916			- NL	ELL S SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S SC S SC W S SC						Performance 🖌			T
Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		+
Body Inspection Comments						Tyres (lowest observed tread	·		
						Left front 7.5			
						Right front	7.5		mm
						Left rear			mm
Conditions During Rody Inspection: West						Right rear	6 6		mm
Conditions During Body Inspection: Wet						Spare	6 11 N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
2wd		-				Suspension performance		~	1
						Steering performance		~	
						Shock absorbers	~	V	
						Air Conditioning / Heater	v		L
						Operation	~		T
Interior Comments						Electrical / Accessories	•		
Seate	Seats Average					Head lights	~		1
Seals						Tail lights	~		
Carpets	Average						~		+
Deve 1	Average					Dashboard warning lights	~		+
Panels						Wipers (front & rear)	-		+
Dashboa	rd Average					Wipers (front & rear) Window winder FL	v		+
							~		+
General (<u>Comments</u>					Window winder FR	~		
Minor vibration on idle further investigation needed/suspension knock from front/steering knock					Window winder RL	~		+	
		5			-	Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		+
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Wet						Central locking	~		+
Engine Timing Mechanism: Cambelt						Remote locking	~		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)	~		<u> </u>
LVIGENCE	or carri bert nepiac	ciriciit. p	NU	11113.		Reversing camera			~
Inspected	d by: Uriah Pepene	Date: 30 Oct 2024							
I have read a	and understood th	is condition c	uide. Name:			Signature:			