

Report ID: 365 Version: 1 30 Oct 2024 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2009	Registration:	FDQ69	Reg Expiry:	29 Jul 2025	Engine	I		1	
WoF Expiry:		Odometer:	112,000 Kms	Good No:	26393161	Oil level	~			
VIN:	JSAEZC21S00428744	Next Service:		Service Histor	y:	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	oration is made	for and mileage	Darte have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:	S	-0		-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	s bla			ZIN		Operation	~			
R = rust PT = paint def				\prod	JUIL	Noise	~			
C = crack				$+ \mathbf{\nabla}$		Clutch	~			
P = pin dent	110				세비	CV joints	~			
* = decals	616			The	EITH	Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	t scuffs S S		D	JUS		Performance	~			
Deskulas		Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyre				
						Left front 5 mm				
						Right front		5	mm	
						Left rear		.5	mm	
Conditions During Body Inspection:						Right rear			mm	
Conditions During Body inspection:						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			<u> </u>	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	A. 1979 8.9					Tail lights	~			
Carpets	Average					Indicators	~			
Panels	Average					Dashboard warning lights	~		<u> </u>	
						Wipers (front & rear)	~		+	
Dashboa	ard Average					Window winder FL	~		<u> </u>	
						Window winder FR	~		+	
General Comments						Window winder RL	~		<u> </u>	
						Window winder RR	~		+	
						Rear view mirrors	~		+	
						Radio (basic test only)	~			
						CD (basic test only)	-		~	
						Number of keys	1			
Road Conditions During Test Drive: Dry Central locking							· •			
						Remote locking		~	<u> </u>	
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~	
[-					-				
Inspecte	Inspected by: Charles Date: 24 Oct 2024									

I have read and understood this condition guide.

Name:

Signature: