

Report ID: 26,396,066 Version: 2 04 Nov 2024 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	<b>Registration:</b>	LKS406	<b>Reg Expiry:</b>	30 Sep 2024	Engine	1		1
WoF Expiry:	26 Apr 2025	Odometer:	152,747 Kms	Good No:	26396066	Oil level	~		
VIN:	MPATFS85JJT005389	Next Service:	144,000 km	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
	SC W		P SC S P		S D R SC	Performance	~		
Key:	ISC IV	-0	P SC S P		SDRSC	Radiator / Hoses (visual)	~		
S = scratch						Transmission	mission		
D = dent R = rust	S SC			715		Operation	~		
PT = paint defe		F		$\left[ \left( \right) \right]$		Noise	~		
C = crack					S P	Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals R P SC 9 9 S D R						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	t scuffs S		S P SC S P SC		S R SC	Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Windscreen chip crack in cva.						<b>Tyres</b> (lowest observed tread depth of tyres)			es)
Rear bumper pushed in.						Left front 5 m			mm
						Right front	5	5	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shc						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories	1		
Seats	Average					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
AC not blowing ice cold. Fault codes.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Imraan Bryant Date: 04 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....