

Basic Vehicle Condition Guide

Report ID: 26,396,646


10 Version:

19 Dec 2024 Created:

Make: Model: Mitsubishi Outlander **Body Style:** SUV Year: 2016 Registration: JRG795 Reg Expiry: 31 Aug 2025 **Odometer:** WoF Expiry: **Good No:** 04 Jul 2025 205,808 Kms 26396646 **Next Service:** VIN: JMFXTGF7WGZ003188 212,000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive,

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Andre Richardson Inspected by:

d: 19) Dec 2	024
Pass	Fail	N/A
	<u></u>	1
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
~		
'		
l depth	of tyre	es)
2	.0	mm
3.0		mm
5.0		mm
5	.0	mm
	Yes	
~		
~		
~		
	T	
~		
	1	
~		
~		
~		
~		
~		
<i>V</i>		
~		
~		
~		
/		
~		
2		
~		
~		
		~
	Pass V V V V V V V V V V V V	Pass Fail

Reversing camera

04 Nov 2024

I have read and understood this condition guide. Name: Signature: