

Basic Vehicle Condition Guide

Report ID: 26,398,858


Version: 1

01 Nov 2024 Created:

Make: Model: Holden Colorado **Body Style:** Utility Year: 2019 Registration: MJS800 Reg Expiry: 02 Mar 2025 WoF Expiry: **Odometer: Good No:** 20 Aug 2025 145,409 Kms 26398858 VIN: MMU148MK0LH6119: Next Service: 153000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine		•	
Oil level	~		
Smoke & fumes	~		
Performance	V V		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		!	
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		7	mm
Right front	7		mm
Left rear	7		mm
Right rear	7		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	1		

Signature:

Kilipati Mae 01 Nov 2024 Inspected by:

Name: