

V Radiator / Hoses (visual) V V V Clutch V P = pin dent CV joints ~ SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs S W Performance V Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front mm 4 **Right front** 4 mm Left rear 5 mm **Right rear** 5 mm Conditions During Body Inspection: Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels V Wipers (front & rear) Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V

Engine Timing Mechanism:Timing ChainEvidence of Cam Belt Replacement:Not Applicable

Inspected by: Kilipati Mae

Date: 01 Nov 2024

Sat. Nav. (basic test only)

Reversing camera

I have read and understood this condition guide.

Name:

Kms:

Signature:

V

~

Report ID: 26,399,311 Version: 1 Created: 01 Nov 2024

Pass

~

V

V

~

N/A

Fail