

Basic Vehicle Condition Guide

Report ID: 26,399,638


Version: 3

Created: 28 Nov 2024

Make: Model: **Body Style:** Toyota Rav4 SUV Year: 2021 Registration: NUC66 Reg Expiry: 14 Jan 2025 WoF Expiry: **Odometer: Good No:** 27 Nov 2025 23,188 Kms 26399638 VIN: JTMBW3FV40D12307(Next Service: Service History: 38000 kms Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

4WD

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Name:

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eleoit Kumar

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance Hand Brake	Pass V V V V V V V V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	\(\times \) \(\t		v
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V V V V V V V V V V V V V V V V		
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V V V V V V V V V V V V V V V V		~
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V V V V V V V V V V V V V V V V		·
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	\(\times \) \(\t		·
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	\(\times \) \(\t		· ·
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V		· ·
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	\(\times \)		v
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	<i>V V V V</i>		·
Operation Noise Clutch CV joints Wheel bearings Brakes Performance	<i>V V V</i>		·
Noise Clutch CV joints Wheel bearings Brakes Performance	ン ン ン		<i>'</i>
Clutch CV joints Wheel bearings Brakes Performance	V V		~
CV joints Wheel bearings Brakes Performance	<i>V</i>		~
Wheel bearings Brakes Performance	✓ ✓		
Brakes Performance	~		I
Performance			
Hand Brake	~		
	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	6	5	mm
Right front		 5	mm
Left rear		7	mm
Right rear		7	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	<i>v</i>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	v		
Wipers (front & rear)	V		
Window winder FL	V		
Window winder FR	· ·		
Window winder RL	·		
Window winder RR	·		
Rear view mirrors	~		
Radio (basic test only)	· ·		
CD (basic test only)	-		1
Number of keys	2		
Central locking	·		
Remote locking	<u> </u>		
Sat. Nav. (basic test only)	<u> </u>		
Reversing camera	_		

28 Nov 2024

Signature:

Date:

			condition	