

Basic Vehicle Condition Guide

Report ID: 26,400,084


Version: 1

04 Nov 2024 Created:

Make: Model: Ssangyong Tivoli **Body Style:** SUV Year: 2015 Registration: JLY799 Reg Expiry: 31 Dec 2024 WoF Expiry: **Odometer: Good No:** 10 Sep 2025 65,458 Kms 26400084 VIN: Next Service: 73000 KPT30B1VSFP041405 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body	Inspection
------------------------	------------

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Good	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

One key fob not working

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Kilipati Mae Inspected by:

V
es 🗸
es v
V
n
ition 🗸
V
ses (visual)
V
V
V
V
gs 🗸
V
· /
bserved tread depth of tyres)
5 mm
6 mm
3 mm
6 mm
Yes
erformance 🗸
ormance 🗸
ers 🗸
ng / Heater
essories
· ·
V
arning lights 🗸
arning lights & rear)
ler FL 🗸
ler FR
ler RR
esconiy) V
only)
only)
only) ys 2 g
rys 2 rg rg rg
only) ys 2 g
ler RL ler RR rors est only)

I have read and understood this condition guide.

Name:

Signature: