

Basic Vehicle Condition Guide

Report ID: 131,104


Version: 1

Created: 13 Nov 2024

Make: Model: CRV Honda **Body Style:** SUV Year: 2018 Registration: LJQ109 Reg Expiry: 30 Jun 2025 WoF Expiry: **Odometer: Good No:** 01 Jun 2025 33,000 Kms 26402869 VIN: MRHRW2850JP06543! Next Service: 47300 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body	Inspection
------------------------	------------

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

07 Nov 2024 Inspected by: Charles Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	>		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4.	.8	mm
Right front	4.8		mm
Left rear	5		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	\(\triangle \)		
Shock absorbers	>		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	'		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	V		
Reversing camera	~		

Signature: