

Report ID: 26,404,731 Version: 2 15 Nov 2024 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	Registration:	LEU780	Reg Expiry:	12 Feb 2025	Engine			
WoF Expiry:	11 Nov 2025	Odometer:	155,711 Kms	Good No:	26404731	Oil level	~		
VIN:	MPBUMFF50HX14785	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	D SD			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust				Γ	THA	Noise	~		
PT = paint def C = crack	ect III			+	D	Clutch			~
P = pin dent	Ho				JIII —	CV joints	~		•
* = decals	sc pip			AL-	ET P	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs DRW						Performance			
		Notor con	ne defects & blemishes				~		
Body Insp	pection Comments	Note: son	le délects & blemisnes	s may not be disp	layed in the diagram	Hand Brake			
Dent in lh c pillar, Dents above rear window. Right a pillar multiple dents					Tyres (lowest observed tread	· ·		-	
						Left front	7.	-	mm
						Right front	7.		mm
						Left rear	7.	-	mm
Conditions During Body Inspection: Dry						Right rear	6.5 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Rh chassis rail has rust bubbling that has been painted over by Rh wheel arches						Suspension	1.		
Rn Chassis r	all has rust bubbling th	at has been pain	ted over by Rh wheel a	arches		Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
Comment						Window winder FR	~		
General Comments						Window winder RL	~		
Mirrors do not retract using button. Aftermarket throttle controller fitted. A/c, nav and reverse camera working at time of inpsection						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
	d hu Doubor Herrer					Date: 06 Nov 20			
Inspected by: Reuben Harvey Date: 06 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: