

Report ID: 26,405,091 Version: 2 19 Nov 2024 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2012	Registration:	GFR595	Reg Expiry:	14 Jan 2025	Engine	I		I
WoF Expiry:	29 Nov 2025	Odometer:	145,024 Kms	Good No:	26405091	Oil level	~		
VIN:	6G1PE6E57CL618485	Next Service:	155000	Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		6	Danta hava nat	harry discovered and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	S	-161-	Р	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			10-	SC SC	Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack						Clutch			~
P = pin dent	HC					CV joints	~		•
* = decals	sc 916				EII PR-	Wheel bearings	~		
SC = stone chi		VA		1al		Brakes	v		
W = significant scuffs SC W S P						Performance	~		
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments		le delects & blemisnes	s may not be disp	ayea in the diagram		-	ofture))
					Tyres (lowest observed tread depth of tyres) Left front 7.0				
							7.		mm
						Right front Left rear	7.		mm
						Right rear	8.	-	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	indge a onder bor	meenspeene	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Concret						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Incracto	Inspected by: John Jones Date: 05 Nov 2024								
Inspected by. John Jones Date: 05 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: