

Basic Vehicle Condition Guide

Report ID: 26,405,206


Version: 1

Created: 08 Nov 2024

Make: Model: Ssangyong Tivoli **Body Style:** SUV Year: 2021 Registration: NGN385 Reg Expiry: 30 Jan 2025 WoF Expiry: **Odometer:** 02 Feb 2025 22,119 Kms **Good No:** 26405206 VIN: **Next Service:** KPT30B1YSLP352750 32000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Comment	<u>s</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Jaykib Collins 08 Nov 2024 Inspected by:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	peration 🗸		
Noise	~		
Clutch			~
CV joints	>		
Wheel bearings	~		
Brakes			
Performance	V		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	(5	mm
Right front	7	7	mm
Left rear	į	5	mm
Right rear	5.5		mm
Spare		Yes	
Suspension			
Suspension performance	v v		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	>		
Wipers (front & rear)	\(\times \)		
Window winder FL	>		
Window winder FR	VVV		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

I have read and understood this condition guide.

Name:			