

## **Basic Vehicle Condition Guide**

Report ID: 26,406,061


Version: 2

Created: 20 Nov 2024

Make: Model: Ssangyong Korando **Body Style:** SUV Year: 2016 Registration: NFJ640 Reg Expiry: 20 Apr 2025 WoF Expiry: **Odometer: Good No:** 15 Jul 2025 50,092 Kms 26406061 VIN: **Next Service:** KPTB0A18SGP240069 60000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Reuben Harvey

Create	u. 20	J 140 V 2	2024
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	l depth	of tyre	⊥ ≥s)
Left front	7.5		mm
Right front	7.5		mm
Left rear	6.0		mm
Right rear	6.0		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			l
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators			
Dashboard warning lights	> > >		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR			
Window winder RL	<i>y</i>		
Window winder RR	\( \times \)		
Rear view mirrors	v		
Radio (basic test only)			
CD (basic test only)	\( \tau \)		
Number of keys	2		
Central locking	4		
Remote locking	•		
			.,
Sat. Nav. (basic test only)  Reversing camera			./
neversing cumera			

I have read and understood this condition guide. Name: ......

Signature: .....

08 Nov 2024

Date: