

Basic Vehicle Condition Guide

Report ID: 26,407,167


Version: 3

Created: 08 Jan 2025

Make: Model: Toyota Corolla **Body Style:** Hatchback Year: 2014 Registration: HHJ643 Reg Expiry: 28 Feb 2025 WoF Expiry: **Odometer: Good No:** 25 Jul 2025 191,132 Kms 26407167 VIN: JTNKU3JE00J053795 Next Service: 182404 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD

Interior Comments					
Seats		Good			
Carpets		Good			
Panels		Good			
Dashboa	rd	Good			

General Comments

Gear shift trim faded.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eleoit Kumar Date: 08 Jan 2025

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•		•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		7	mm
Right front	7		mm
Left rear	5		mm
Right rear	3		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	· ·		
Remote locking	~		
Sat. Nav. (basic test only)	<u> </u>		V
Reversing camera			<i>y</i>
eversing cumera			

Signature: