

Report ID: 26,407,872 Version: 1 19 Nov 2024 Created:

Make:	Toyota	Model:	Estima	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2007	<b>Registration:</b>	JSA259	<b>Reg Expiry:</b>	16 Mar 2025	Engine				
WoF Expiry:	12 Jun 2025	Odometer:	177,307 Kms	Good No:	26407872	Oil level	~			
VIN:	7AT0H61YX16052913	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~			
	PT SC		SC S SC		PT SC W	Performance	~			
Key:	LET SC L	-0			FISCW	Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust	s sc w			710	S SC W	Operation	~			
PT = paint def	ect NP				70111	Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	sc dP				74116	CV joints	~			
* = decals				10	S SC	Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
	SC W		SC S PT SC		SC	Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)				
						Left front	2	.6	mm	
						Right front	3	.4	mm	
						Left rear	3	.6	mm	
Conditions During Body Inspection: Dry						Right rear	4	4.1 n		
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
No underbo	ody inspection					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	small hole	, wear				Head lights	~			
Correcto	marks					Tail lights	~			
Carpets						Indicators	~			
Panels	scratches,	wear				Dashboard warning lights	~			
Dachher-	wear steer	ing wheel and g	ear knob			Wipers (front & rear)	~			
Dashboa	iiu					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)		~		
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
с <u> </u>		<del></del>	21 <b>.</b> .			Remote locking	~			
-	ming Mechanism:	Timing (				Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspector	Inspected by: Melissa Wilson Date: 19 Nov 2024									

I have read and understood this condition guide.

Name: .....

Signature: .....