

Report ID: 26,407,893 Version: 1 12 Nov 2024 Created:

Make:	Volkswagen	Model:	Cross Polo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2018		LHL600	Reg Expiry:	15 Dec 2024	Engine			L
WoF Expiry:		Odometer:	88,617 Kms	Good No:	26407893	Oil level	~		
VIN:	WVWZZZ6RZHU0829	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			1n-		Operation	~		
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	sc 916			AL.	HIP I	Wheel bearings	~		
SC = stone chi	/	2 M		(a)		Brakes	•		L
W = significant	t scuffs	-				Performance	~		
			ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	Note: 5011		indy not be disp	ayea in the diagram		-	oftyre	<u> </u>
						Tyres (lowest observed tread depth of tyres)			
						Left front	3.		mm
						Right front Left rear	4.	-	mm
							5.		mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbe							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Average						Electrical / Accessories			
Seats	, weitige					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		-
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
Concret	ommonts					Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine T:	ming Machanian	Combal	•			Remote locking	~		
-	ming Mechanism:	Cambel		IZ.		Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
Inspected	d by: Greg Morgan					Date: 07 Nov 20	24		
Inspected									

I have read and understood this condition guide.

Name:

Signature: