

Basic Vehicle Condition Guide

Report ID: 26,408,416


Version: 2

Created: 13 Nov 2024

Make: Model: Holden Colorado **Body Style:** Utility Year: 2016 Registration: QWZ26 Reg Expiry: 01 May 2025 WoF Expiry: **Odometer: Good No:** 01 Nov 2025 167,478 Kms 26408416 VIN: MMU148LK0GH62492 Next Service: 177500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------------------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | torn steering wheel | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Not Applicable Kms: 167,540

06 Nov 2024 Inspected by: Sione Mae Date:

Name:

| | Pass | Fail | N/A | |
|--|-----------------|------|-----|--|
| Engine | • | • | | |
| Oil level | ~ | | | |
| Smoke & fumes | v | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | • | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | • | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 7 | .0 | mm | |
| Right front | 7.0 | | mm | |
| Left rear | 7.0 | | mm | |
| Right rear | 7 | .0 | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | V V V V V V V V | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |

Signature: