

S = scratch		Radiator / Hoses (visual)	~	
		Transmission		
R = rust		Operation	~	
PT = paint defect		Noise	~	
C = crack	S R SC	Clutch		~
P = pin dent		CV joints	~	
		Wheel bearings	~	
SC = stone chips		Brakes		
W = significant scuffs	P S SP SRSC	Performance	~	
Body Inspection C	Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
Right front fog light d	Tyres (lowest observed tread depth of tyres)			
Stone chips in windscreen		Left front	3.0 mm	
		Right front	3.0	mm
		Left rear	5.5	mm
Conditions During Body Inspection: Wet		Right rear	5.5	mm
		Spare	Yes	
Under Carriage &	Suspension			
		Suspension performance	~	
		Steering performance	~	
		Shock absorbers	~	
		Air Conditioning / Heater		
		Operation	~	
Interior Comments		Electrical / Accessories		
Seats	Good	Head lights	~	
	Good	Tail lights	~	
Carpets		Indicators	~	
Panels	Good	Dashboard warning lights	~	
	Good	Wipers (front & rear)	~	
Dashboard		Window winder FL	~	
	J	Window winder FR	~	
General Commen	<u>ts</u>	Window winder RL	~	
		Window winder RR	~	
		Rear view mirrors	~	
		Radio (basic test only)	~	
		CD (basic test only)	~	
		Number of keys	2	I
Road Conditions During Test Drive: Dry		Central locking	~	
		Remote locking	~	
Engine Timing Me	Sat. Nav. (basic test only)	· ·		
Evidence of Cam Belt Replacement: Not Applicable Kms:		Reversing camera	~	
Inspected by: Sar	nuel Weir	Date: 15 Nov 20	24	

Name: .....

2

Pass

V

V

V

V

V

V

26 Nov 2024

Fail

N/A