

Basic Vehicle Condition Guide

Report ID: 26,409,080


Version: 4

Created: 11 Jan 2025

Make: Model: Mitsubishi L300 **Body Style:** Van Year: 2013 Registration: GTJ262 Reg Expiry: 25 Sep 2025 **Odometer:** WoF Expiry: 29 Jul 2025 167,205 Kms **Good No:** 26409080 VIN: JMASNP04VDA800352 Next Service: 176,000 kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Rust roof and underbody.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Marlon Espena Date: 18 Nov 2024

		ı		
	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	<i>V V</i>			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed treac	depth	of tyre	es)	
Left front	3	.9	mm	
Right front	3	.9	mm	
Left rear	4	.8	mm	
Right rear	4	.9	mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories				
Head lights	~			
Tail lights				
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\times \)			
Window winder FL	~			
Window winder FR	VVV			
Window winder RL	· ·			
Window winder RR	· ·			
Rear view mirrors	~			
Radio (basic test only)				
CD (basic test only)	~			
Number of keys	-			
<u> </u>	1		.,	
Central locking				
Remote locking				
Sat. Nav. (basic test only)				
Reversing camera				

I have read and understood this condition guide.

Name:

Signature: