

| | | |
|--------------------------------|------------------------------|--------------------------------|
| Make: Foton | Model: Tunland | Body Style: Utility |
| Year: 2016 | Registration: QWJ520 | Reg Expiry: 22 Mar 2025 |
| WoF Expiry: 20 Mar 2025 | Odometer: 134,809 Kms | Good No: 26410488 |
| VIN: LVAV2MBBXFJ051179 | Next Service: 140,000 | Service History: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram
Daytime running light have been painted black & LH not working, Headlamps cloudy, Light bar fitted to nudge bar, Paint coming off both wing mirrors, LH/R flare coming off, Rust in rear of tray, Paint faded on roof, Aerial broken, LH/R fog lamp cracked & pushed into bumper,

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments
Rear wheel drive, LH/F tyre worn on outside edge, Differential leaking, Oil filter housing leaking, Engine oil leaking from rear of head, Thermostat housing leaking

Interior Comments

| | |
|-----------|---------|
| Seats | Average |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments
Remote buttons worn & not working, Fuse box cover missing, Unable to open glovebox due to handle broken off, Rear seats stained, Wipers need replacing, All tints have faded to clear, Vehicle pulls left, Tailgate handle broken & won't open.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A |
|---|------|------|-----|
| Engine | | | |
| Oil level | ✓ | | |
| Smoke & fumes | ✓ | | |
| Performance | ✓ | | |
| Noise | ✓ | | |
| Cooling System | | | |
| Coolant condition | ✓ | | |
| Performance | ✓ | | |
| Radiator / Hoses (visual) | | ✓ | |
| Transmission | | | |
| Operation | ✓ | | |
| Noise | ✓ | | |
| Clutch | ✓ | | |
| CV joints | | | ✓ |
| Wheel bearings | ✓ | | |
| Brakes | | | |
| Performance | ✓ | | |
| Hand Brake | ✓ | | |
| Tyres (lowest observed tread depth of tyres) | | | |
| Left front | 3 | mm | |
| Right front | 4 | mm | |
| Left rear | 4 | mm | |
| Right rear | 4 | mm | |
| Spare | | Yes | |
| Suspension | | | |
| Suspension performance | ✓ | | |
| Steering performance | ✓ | | |
| Shock absorbers | ✓ | | |
| Air Conditioning / Heater | | | |
| Operation | ✓ | | |
| Electrical / Accessories | | | |
| Head lights | ✓ | | |
| Tail lights | ✓ | | |
| Indicators | ✓ | | |
| Dashboard warning lights | ✓ | | |
| Wipers (front & rear) | | ✓ | |
| Window winder FL | ✓ | | |
| Window winder FR | ✓ | | |
| Window winder RL | ✓ | | |
| Window winder RR | ✓ | | |
| Rear view mirrors | ✓ | | |
| Radio (basic test only) | ✓ | | |
| CD (basic test only) | ✓ | | |
| Number of keys | 1 | | |
| Central locking | ✓ | | |
| Remote locking | | ✓ | |
| Sat. Nav. (basic test only) | | | ✓ |
| Reversing camera | | | ✓ |

Inspected by: Andre Richardson Date: 14 Nov 2024

I have read and understood this condition guide. Name: Signature: