

Report ID: 26,410,670 Version: 1 13 Nov 2024 Created:

Make:	Skoda	Model:	Octavia	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	Registration:	HNS470	Reg Expiry:	27 Jul 2025	Engine			
WoF Expiry:	11 Sep 2025	Odometer:	169,566 Kms	Good No:	26410670	Oil level	~		
VIN:	TMBKJ7NE7E0178952	Next Service:	177,150kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	P D	$- \square$		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SC W			715	HIL S	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				게	CV joints	~		-
* = decals	sc 916			The	HIP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S D D W						Performance	~		
Dealerteen	<u></u>	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection Comments						Tyres (lowest observed tread		of tvre	es)
Dent on left sill. Small stone crack on windscreen						Left front 3.0 mm			
						Right front	3.		mm
						Left rear	5.		mm
Condition	as During Body Ins	noction:				Right rear	5.		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Weeping fr	om around right side of	engine oil pan a	nd cooling line.			Suspension performance	~		
	-	5 .	-			Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		l
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Right side of driver's seat base trim is worn.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	-	lot Applicable	Kms:		Reversing camera			~
	•		••						-
Inspected by: Yuki Itohara Date: 07 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: