

Basic Vehicle Condition Guide

Report ID: 26,410,932


Version: 2

Created: 27 Nov 2024

Make: Model: Hyundai lload **Body Style:** Van Year: 2018 Registration: LGC186 Reg Expiry: 07 Mar 2025 WoF Expiry: **Odometer: Good No:** 27 Nov 2025 83,532 Kms 26410932 VIN: KMFWBX7KMJU93194 Next Service: 91,000 kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Boot interior seal torn

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Rwd

Interior Commen	<u>ts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

	_
General	Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Inspected by:	Vasanthakumar	Mayilswamy
---------------	---------------	------------

I have read and understood this condition guide.

Creater	u. 2	7 INOV 2	
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	/		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	-		1
Performance	/		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	
Left front		.0	mm
Right front	7.0		mm
Left rear	5.0		mm
Right rear	4.0		mm
Spare	7	Yes	
Suspension		103	
Suspension performance	V		
Steering performance	· ·		
Shock absorbers	•		
Air Conditioning / Heater			
Operation Electrical / Accessories	•		
Head lights			1
Tail lights	<i>'</i>		
Indicators	•		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	•		
Window winder FL	•		
Window winder FR	-		
Window winder RL			-
Window winder RR			-
Rear view mirrors	/		
Radio (basic test only)	~		
CD (basic test only)			'
Number of keys	2		
6	~		
Central locking			
Remote locking	>		
	<i>'</i>		~
Remote locking	<i>y</i>		'