

Basic Vehicle Condition Guide

Report ID: 26,411,600


Version: 1

Created: 12 Nov 2024

Make: Model: Suzuki Ignis **Body Style:** SUV Year: 2019 Registration: MCU857 Reg Expiry: 29 Oct 2024 WoF Expiry: **Odometer: Good No:** 20 Mar 2025 58,354 Kms 26411600 VIN: JSAMFH11S00217571 **Next Service:** 68000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

Interior Commo	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Fresh WOF

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jaykib Collins Date: 08 Nov 2024

5.	of tyre	· ·
v v v v v v v v v v v v v v v v v v v	of tyre	v
v v v v v v v v v v v v v v v v v v v	of tyre	·
v v v v v v v v v v v v v v v v v v v	of tyre	· ·
v v v v v v v v v v v v v v v v v v v	of tyre	V
v v v v v v v v v v v v v v v v v v v	of tyre	~
v v v v v v v v v v v v v v v v v v v	of tyre	· ·
v v v v v v v v v v v v v v v v v v v	of tyre	~
v v v v v v v v v v v v v v v v v v v	of tyre	~
depth	of tyre	<i>'</i>
depth	of tyre	<i>'</i>
depth	of tyre	~
depth	of tyre	<i>'</i>
depth	of tyre	
5.	of tyre	
		:s)
	.0	mm
5.5		mm
5.	.5	mm
		mm
/		
~		
/		
/		
/		
/		
/		
~		
V		
~		
· /		
· ·		
· ·		
· ·		
•		V
2		
·		
·		
•		
	5.	5.5 6.0 Yes V V V V V V V V V V V V V V V V V V

I have read and understood this condition guide.

Name:

Signature: