

Basic Vehicle Condition Guide

Report ID: 26,413,185


Version: 2

Created: 12 Nov 2024

Make: Model: Mazda Axela **Body Style:** Hatchback Year: 2013 Registration: MQW353 Reg Expiry: 12 Nov 2024 WoF Expiry: **Odometer: Good No:** 07 Jun 2025 139,082 Kms 26413185 VIN: Next Service: 145000 7AT0C13JX19992693 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Loose middle console lid

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Sharon Waaka 12 Nov 2024 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		7	mm
Right front	front 7		mm
Left rear	7		mm
Right rear	7		mm
Spare		No	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	V V V V V		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	1		

Signature: