

I have read and understood this condition guide.	Name:

Conditions During Body Inspection:

Interior Comments

Seats

Carpets

Panels

Dashboard

General Comments

Road Conditions During Test Drive:

Evidence of Cam Belt Replacement:

Gary Adams

Engine Timing Mechanism:

Inspected by:

Under Carriage & Under Bonnet Inspection Comments

Average

Average

scratches

Dry

both side coming apart along window rear edge

Dry

Not Applicable

Kms:

Timing Chain

12 Nov 2024

Right front

Left rear

Right rear

Suspension

Operation

Head lights

Tail lights

Indicators

Suspension performance

Steering performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL

Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date:

Shock absorbers

Spare

7.0

7.0

7.0

1

V

~

V

1

1

~

1

1

V

V

V

V

~

V

V

2 V

V

V

~

Yes

mm

mm

mm

Signature: