

Report ID: 26,415,794 3 Version: 14 Dec 2024 Created:

Make:	BMW	Model:	5281	Body Style:	Wagon		Pass	Fail	N/A
Year:	2013	Registration:	NAP680	Reg Expiry:	02 Dec 2024	Engine	I		L
WoF Expiry:	18 Sep 2025	Odometer:	105,605 Kms	Good No:	26415794	Oil level	~		
VIN:	WBAXL32020C94167!	Next Service:	115000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		$- \alpha^{\vee}$		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				+		Clutch			~
P = pin dent	HID				게비	CV joints			V
* = decals	616			-Jul-		Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant	t scuffs	$\neg \varnothing$	<u> </u>	JYW		Performance	~		
Bodylag		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front 4.0 n			mm	
						Right front	4	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection:						Right rear	4.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	r		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central lock							~		
						Remote locking	~		
-	ming Mechanism:	Timing (Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Kilipati Mae Date: 11 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: