

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2008	Registration:	ENF258	Reg Expiry:	01 Apr 2025	Engine			
WoF Expiry:	09 Mar 2025	Odometer:	218,356 Kms	Good No:	26416742	Oil level	~		
VIN:	JN1CPUD22A0022639	Next Service:	228,800kms	Service Histor	y: No	Smoke & fumes	~		
Note: This report is not a warranty						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
			ins can be analiged to		indige.	Coolant condition	~		
Kan	S SC S	5	SDP SDP	\sim		Performance	~		
Key: S = scratch		$\overline{(0)}$		5(O)7		Radiator / Hoses (visual)	~		
						Transmission			
R = rust S P P						Operation	~		
PT = paint def	ect N	1			S D SC	Noise	~		
C = crack					S D SC	Clutch	~		
P = pin dent	sscw dl				74Hb	CV joints	~		
* = decals SC = stone chi		10		70		Wheel bearings	~		
W = significant scuffs						Brakes			
SC S SDP DP						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	9	.0	mm
						Right front	9	.0	mm
						Left rear	3	.2	mm
Conditions During Body Inspection: Dry						Right rear	3.0 m		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak around front crank p	ulley on front of	engine block.			Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments Screw holes in dashboard & right side of centre console. Cd player is not working.						Window winder RL	~		
Screw holes	s in dashboard & right s	ide of centre cor	isole. Co player is not v	vorking.		Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	2		
Road Con	ditions During Tes	Drive:	Dry			Central locking	~		
Remote locking									~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Young Date: 13 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: