

Basic Vehicle Condition Guide

Report ID: 26,418,791


Version: 3

Created: 20 Nov 2024

Make: Model: Suzuki Splash **Body Style:** Hatchback Year: 2010 Registration: KTD563 Reg Expiry: 16 Nov 2025 WoF Expiry: **Odometer:** 01 Nov 2025 126,307 Kms **Good No:** 26418791 VIN: TSMEXB32S00350872 Next Service: 135,280 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	Poor, Burn holes in driver's seat	
Carpets	Good	
Panels	Good	
Dashboard	Good	

General Comments

Head unit doesn't work.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Caleb Spicer Lee Inspected by: 12 Nov 2024 Date:

SS	Fail	N/A	
,			
,			
,			
,			
	1		
,			
,			
,			
Performance Radiator / Hoses (visual)			
,			
,			
		~	
,			
,			
,			
,			
pth	of tyre	 es)	
	5.0	mm	
5.0		mm	
1.5		mm	
3.0		mm	
	Yes		
	103		
,			
,			
,			
,			
,			
,			
,			
, , ,			
,			
,			
,			
		'	
		~	
		'	
	_		

I have read and understood this condition guide.

Name:

Signature: