

Report ID: 26,419,089 Version: 3 25 Nov 2024 Created:

Signature:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	Registration:	FWA737	Reg Expiry:	04 Jul 2025	Engine			L
	21 Feb 2025	Odometer:	247,560 Kms	Good No:	26419089	Oil level	~		
VIN:	MNALS2E90AW91512	Next Service:	257,555 Kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		< L			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		
		_				Performance	~		<u> </u>
Key:	S SC S	-0	s sc sc		SC	Radiator / Hoses (visual)	~		<u> </u>
S = scratch						Transmission			
D = dent SC 66 SDCSC						Operation V			T
R = rust				10	JHIK	Noise	~		
PT = paint def C = crack	ect M		-	+	S SC	Clutch			
C = Crack P = pin dent	Ho						~		
* = decals SC QQ SD SD SC W						CV joints	~		
SC = stone chips						Wheel bearings	5		
W = significant scuffs S SC S SC S SC S SC S						Brakes			
						Performance	~		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Chips left A pillar. Left front step plate worn.						Tyres (lowest observed tread depth of tyres)			
Rear bumper cover needs refitted. Right rear window bung missing. Right front step plate worn. Aerial bent.						Left front	8.	0	mm
Rust chips and scratches on roof.						Right front	8.	0	mm
						Left rear	3.	0	mm
Conditions During Body Inspection: Dry						Right rear	2.5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	right front	seat back torn				Head lights	~		
	Average					Tail lights	~		
Carpets	Weldge					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
	h - 1 2 1	, holes in dash				Wipers (front & rear)	~		
Dashboa	rd noies in da	1511				Window winder FL	~		+
					I	Window winder FR	~		<u> </u>
General Comments						Window winder RL	-		~
						Window winder RR			~
						Rear view mirrors	~		-
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			
	1		_			Number of keys	1		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Ti	ming Mechanism:	Cambelt				Remote locking			~
Evidence of Cam Belt Replacement: Yes Kms: 187,000						Sat. Nav. (basic test only)			~
LYNCEHICE	or carri bert nepiac	ciriciit. Y	53	10113. [Ö	,000	Reversing camera			~
Inspected by: Dean Sinclair Date: 12 Nov 2024									

I have read and understood this condition guide.

Name: