

Report ID: 26,419,247 Version: 1 27 Nov 2024 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	Registration:	HJU652	Reg Expiry:	07 May 2025	Engine			
WoF Expiry:	20 Nov 2025	Odometer:	249,620 Kms	Good No:	26419247	Oil level	~		
VIN:	KMHST81XSEU267637	Next Service:		Service Histor		Smoke & fumes	~		
			20000			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
		_				Performance	~ ~		
Key:	DSC	-0	D PT SC PT			Radiator / Hoses (visual)	~		
S = scratch	Se	20		10/2	\mathbf{x}	Transmission	V		
D = dent	s sc			1 - L	HID S				
R = rust				10		Operation	~		
PT = paint defe	ect M			$\square \cup$	SC	Noise	~		
C = crack P = pin dent	Ht			-		Clutch			~
* = decals	R SC DC					CV joints	~		
SC = stone chi	ps US			10		Wheel bearings	~		
W = significant scuffs S D S PT SC S D						Brakes			1
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Minor stone chips on windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	3.	5	mm
						Right front	4.	0	mm
						Left rear	2.	5	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
All wheel d	rive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at torn, Good				Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments					Window winder RL	~			
Hole under	leather of centre conso	le				Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
	uning res		Dry			Remote locking	~ ~		
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
Inspected by: Jaykib Collins Date: 13 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: