

Report ID: 26,420,288 Version: 1 14 Nov 2024 Created:

Make:	Holden	Model:	Malibu	Body Style:	Sedan		Pass	Fail	N/A
Year:	2013	Registration:	HCS844	Reg Expiry:	30 Oct 2025	Engine			
WoF Expiry:	06 Jun 2025	Odometer:	233,371 Kms	Good No:	26420288	Oil level	~		
VIN:	KL3GA69U9DB081606	Next Service:	232000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		S D S D		S D	Performance	~		
Key:	La C	-0	30 30		30	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack					SC	Clutch			~
P = pin dent	In the				7414	CV joints	~		
* = decals S D SC 9 9 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC PT S P SC						Performance		~	
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
					Left front 5.8 mm				
						Right front		.2	mm
						Left rear		2.8 mm	
Conditions During Body Inspection: Wet						Right rear	7.0 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers						Shock absorbers	~		
Air Conditi									
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	wear,rippe	ed,				Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	~		
Vibration o	n braking					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	
Road Con	Central locking	~							
			Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Unknow	/n			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
								1	
Inspected by: Donovan Matara Date: 12 Nov 2024									

I have read and understood this condition guide.

Name:

Signature: