

I have read and understood this condition guide.

Report ID: 26,420,371 3 Version: 12 Dec 2024 Created:

Signature: .....

Make:	Volkswagen	Model:	Crafter	Body Style:	Van		Pass	Fail	N/A
Year:	2023	<b>Registration:</b>	PSS320	Reg Expiry:	07 Mar 2025	Engine	I		L
WoF Expiry:	08 Feb 2026	Odometer:	31,241 Kms	Good No:	26420371	Oil level	~		
VIN:	WV1ZZZSYZN9047181	Next Service:	50,000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-	S	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defect						Noise	~		
						Clutch	•		~
P = pin dent						CV joints	~		
* = decals SC 919 SP						Wheel bearings	v		
SC = stone chips						Brakes			
W = significant scuffs S P S P						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)			 (کد
Reverse camera broken.									mm
Hi stop light cracked. Windscreen crack in cva.						Right front	5.	-	 mm
windscreer	I CIACK III CVA.					Left rear	7		mm
Conditions During Rody Inspection:						Right rear		-	 mm
Conditions During Body Inspection: Dry						Right rear 7.0 mm Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	•				Suspension performance	~		
FWD.						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
						Head lights	~		
Seals	Good					Tail lights	~		
Carpets	Good						~		
Panels	Good					Dashboard warning lights Wipers (front & rear)	レ レ		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	-		
General (	Comments					Window winder FR	~		
						Window winder RL			く く
						Rear view mirrors	~		~
						Radio (basic test only)	~		
						CD (basic test only)	V		
						Number of keys	2		~
						· · · · · · · · · · · · · · · · · · ·			
Road Conditions During Test Drive: Dry						Central locking Remote locking	<b>v</b>		
Engine Timing Mechanism: Cambelt							~		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
		N				Reversing camera	~		
Inspected by: Imraan Bryant Date: 04 Dec 2024									

Name: .....